



**TDX CONSTRUCTION CORPORATION**

Baruch College Field Office 137 East 25th Street, 6th Floor, New York, NY 10010

212 679 0031  
212 679 0037 FAX  
[www.tdxconstruction.com](http://www.tdxconstruction.com)

*We must bring up a claim with a meeting with Bar-Tek.*

May 13, 2002

ND# 1686

Trataros Construction Corporation  
55 Lexington Avenue  
New York, NY 10010

Attn: Athena Curtis

RE: Baruch College - Site "B"  
Uplifting Terrazzo Repairs

This is a response to your memorandum of 4/16/02 requesting a change order to repair the Uplifting Terrazzo. Your request is hereby denied since it is your responsibility to ensure that the substrate is acceptable to receive the Terrazzo. If the conditions are not acceptable, then the Terrazzo should not have been poured. The specification stated that "start of work shall imply acceptance of surfaces to install the epoxy Terrazzo."

In addition, it is also your responsibility to properly prepare the substrate as per spec. Section 09420 paragraph 3.02 If contaminants and or dust are encountered.

Reimbursement for this work should be between Trataros, Crocetti and or Bar-Tek.

We remain,

Very truly yours,  
TDX Construction Corporation

  
Ray Leu

Project Manager

RL/qtw

Cc: N. D'Ambrosio

T. Mockler

J. Jones Jr.

J. Dernase

ND# 1686

*ltr Trataros uplifting terrazzo repairs ND#1686*